ABSTRACT

A method of forming a vertical cavity surface emitting laser (100, 600, 900) includes process steps for selfaligning the p-type ohmic contact (118, 518, 932), an oxide current aperture (122, 926a), and a central puck of rephase material (560a, 936) around the optical axis of the laser.